INSTALLATION RESTORATION PROGRAM

Final DECISION DOCUMENT UST SITE 211

117th Refueling Wing Alabama Air National Guard Birmingham Airport Birmingham, Alabama

January 1997



19970915 073

DITC QUALITY INSPECTED &

Reproved the professolences

Decoration Unimared

REPORT DOCUMENTATION PAGE

Form Approved OMB No. 074-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of the collection of information, including suggestions for reducing this burden to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

1. AGENCY USE ONLY (Leave blank)	2. REPORT DATE Jan 97	3. REPORT TYPE	AND DATE COVERED					
4. TITLE AND SUBTITLE DECISION DOCUMENT, UST 23 Air National Guard, Birms Alabama	11, 117 TH REFUELING WIN ingham Airport, Birmin							
6. AUTHOR(S) CH2M Hill, Inc.								
7. PERFORMING ORGANIZATION NAME(S)	AND ADDRESS(ES)		8. PERFORMING ORGA	NIZATION REPORT NUMBER				
CH2M Hill, Inc.	Hazardous Waste Remed Actions Program, Mart Marietta Energy Syste Oak Ridge, TN 37840							
9. SPONSORING/MONITORING AGENCY NA	ME(S) AND ADDRESS(ES)		10. SPONSORING/MON	ITORING AGENCY REPORT NUMBER				
ANG/CEVR 3500 Fetchet Ave Andrews AFB MD 20762- 5157		·						
11. SUPPLEMENTARY NOTES This is part of IRP Site 13 (ST13) at Birmingham IAP.								
12a. DISTRIBUTION/AVAILABILITY STATEM unlimited distribution	ENT		12b. DISTRIBUTION CODE					
The Installation Restoration Program was initiated by the Air National Guard (ANG) to evaluate potential contamination to the environment caused by past practices at its installations. During the 1987 Preliminary Assessment (PA), ten abandoned underground storage tanks (USTs) were identified at nine sites. During the 1991 Site Investigation, geophysical surveys located two areas believed to contain the USTS. Upon excavation, no USTs were found at either location south of Building 211. The report documents no further action need be taken at this the UST site.								
14. SUBJECT TERMS Installation Restoration Decision Document, UST, 1 Airport, Air National Gu	Birmingham Internation	15. NUMBER OF PAGES 14 pages 16. PRICE CODE						

17. SECURITY CLASSIFICATION OF REPORT

18. SECURITY CLASSIFICATION OF THIS PAGE General General

19. SECURITY CLASSIFICATION OF ABSTRACT General

20. LIMITATION OF ABSTRACT

INSTALLATION RESTORATION PROGRAM

DECISION DOCUMENT SITE UST 211

117 AIR REFUELING WING ALABAMA AIR NATIONAL GUARD BIRMINGHAM AIRPORT BIRMINGHAM, ALABAMA

Submitted to:

AIR NATIONAL GUARD READINESS CENTER ANDREWS AIR FORCE BASE, MARYLAND

Modified and Submitted by:

HAZARDOUS WASTE REMEDIAL ACTIONS PROGRAM MARTIN MARIETTA ENERGY SYSTEMS, INC. OAK RIDGE, TENNESSEE

for the
U.S. DEPARTMENT OF ENERGY
UNDER CONTRACT NO. DE-AC05-840R21400

Prepared by:

CH2M HILL, INC. MONTGOMERY, ALABAMA

JANUARY 1997

DTIC QUALITY INSPECTED 8

Copies of this report may be purchased from the:

National Technical Information Service 5285 Port Royal Road Springfield, Virginia 22161

Federal Government agencies and contractors registered with the Defense Technical Information Center should direct requests for copies of this report to:

Defense Technical Information Center 8725 John J. Kingman Road, Ste 0944 Ft. Belvoir, VA 22060-6218

CONTENTS

Acro:	nyms . utive Sı					• •			• • •			•	• •	• •		• •									iii 1
1.		luction																							
2.		ground										•					•					•			2
	2.1	Program Ba	ckgroun	id.	• • •	• •	• •	• •	•	• •		•		• •	•	• •	•	• •	•		• •	•	• •	• •	2
	2.2	Site Descrip	otion			• •	• •			•		•		• •	•		•		•	• •	• •	•	• •	• •	2
	2.3																								
	2.4	Tank Remo	val Obs	erva	tion	S				• •		•		•	•		•	• •	•			•			6
3.	Contr	ol Measures															•		•			•			8
4.	Conc	lusions							• •			•		•			•		•			•			8
Appe	ndix:	ADEM Res	sponse t	o Cl	losui	re A	As	ses	sm	er	ıt	R	ер	ort	;										
FIGU	IRES				,						,														
1	Alaba	ma Air Natio	onal Gu	ard :	Loca	atio	n	M	ap.																3
2	UST	Location Ma	р																			:			4
3		211 Site Map																							

ACRONYMS

AANG Alabama Air National Guard

ADEM Alabama Department of Environmental Management

ANG Air National Guard

ANGRC Air National Guard Readiness Center

DOD Department of Defense
DOE Department of Energy
GPR Ground Penetrating Radar

HAZWRAP Hazardous Waste Remedial Actions Program

IRP Installation Restoration Program

NGB National Guard Bureau

PA/SI Preliminary Assessment/Site Investigation

RD/RA Remedial Design/Remedial Action

RI/FS Remedial Investigation/Feasibility Study

SI Site Investigation

UST Underground Storage Tank VOC Volatile Organic Compound

EXECUTIVE SUMMARY

As part of the Installation Restoration Program (IRP), the Air National Guard Readiness Center (ANGRC), previously known as the National Guard Bureau (NGB), and Alabama Air National Guard (AANG) requested field observation and sampling during the removal of Underground Storage Tank (UST) 211. The investigation was begun to determine the presence or absence of contamination and the risk to public health and environment, if any, associated with past operations at this site.

This document was prepared to review the available data, to evaluate alternative actions, to make recommendations concerning future action, and to fulfill the requirements and objectives of the National Environmental Policy Act.

The UST 211 site was investigated during the field survey task, and two areas that were believed to contain USTs were found. These areas were excavated during the tank removal project, but no tanks were found.

The Alabama Department of Environmental Management (ADEM) issued a letter in May, 1991 stating that it would not require further action at this site. Because no UST was found, it is recommended that this site be removed from further IRP activities and that no further action be required.

1. INTRODUCTION

The objectives of the Decision Document are to present the history of Underground Storage Tank (UST) 211 at Birmingham's Alabama Air National Guard (AANG) facility, to discuss observations made while investigating the tank, and to present conclusions and decisions about the disposition of each UST site. Decisions are based on regulations set forth in the site investigation (SI) work plan dated November 1989.

Figure 1 shows the general location of AANG facility in Birmingham. Figure 2 shows the specific location of UST 211 on the base. Evaluations are based on criteria set forth in the <u>Site Investigation Work Plan</u>, Alabama Air National Guard (CH2M HILL, Inc., November 1989).

2. BACKGROUND

2.1 PROGRAM BACKGROUND

The Air National Guard Readiness Center (ANGRC), through the Air National Guard (ANG), initiated an Installation Restoration Program (IRP) in response to the policies of the Department of Defense (DOD). The IRP was developed as a phased program for identifying and addressing environmental contamination caused by past practices at ANG installations.

As a part of the IRP, the ANGRC entered into an interagency agreement with the Department of Energy (DOE), under which the DOE will provide technical assistance for implementing this program. The Hazardous Waste Remedial Actions Program (HAZWRAP), as a DOE contractor, is responsible for managing this effort under the interagency agreement.

The IRP, along with other national hazardous waste cleanup programs, follows the terminology and procedures of the National Contingency Plan:

- PA/SI Preliminary Assessment/Site Investigation
- RI/FS Remedial Investigation/Feasibility Study
- RD/RA Remedial Design/Remedial Action

This Decision Document is written to provide the basis for the decision not to do any further work.





FIGURE 1
ANG LOCA 110N CESTRIES
Birmingham, Alabama

3



2.2 SITE DESCRIPTION

The 117th Tactical Reconnaissance Wing is located next to and north of the Birmingham Municipal Airport, Birmingham, Alabama. This AANG installation has been active at its present location since 1938. Through the years, the base has had several missions, with past and present operations involving the use of USTs for containment of heating fuels, diesel fuels, and jet propulsion fuels.

UST 211 was assumed to be a gasoline tank based on information found during the initial investigation of the AANG facility. Tank age could not be determined from base records, but the estimated last use was in 1946. Figure 3 shows the UST 211 site map.

2.3 ENVIRONMENTAL SETTING

2.3.1 Geology

The bedrock beneath the Base consists of the Ketona Dolomite and Knox Group. A mottled-colored cherty clay residuum, resulting from the dissolution of the bedrock, overlies dolomites of these units and averages 30 feet in thickness over the base. Some areas of the Base have visible outcrops of dolomite and chert boulders which are isolated in the clay residuum; chert float can be seen at the surface base-wide.

The residual cherty clays are generally homogeneous, although slight changes in the amount of chert, plasticity and stiffness are present. Dolomitic sand lenses are gravelly clays are present, generally occurring at the contact of clay and bedrock.

2.3.2 Hydrogeology

The uppermost aquifer at the Base is the Knox aquifer. The top of the aquifer is the saturated permeable interface between the residual clay and the bedrock. The clay materials above the bedrock are also generally saturated at shallow depths, 10 to 15 feet below land surface. These clays generally do not yield significant quantities of water.

The direction of groundwater flow in both the clay residuum and the Knox is to the south; a downward vertical component exists in the clay residuum. Data from slug testing of monitoring wells completed in the clay indicate an average hydraulic conductivity of 9.02E-4 ft/day. Because of the low permeabilities exhibited by the residual clays, lateral transport is inhibited.

2.3.3 Water Utilization

Drinking water in the Birmingham is provided by city/county utilities from surface water sources. The municipal water source nearest the Base is the Cahaba River, located approximately 20 miles to the east. Residences adjacent to the Base have been served by the municipal water system for about 60 years.

2.4 TANK REMOVAL OBSERVATIONS

A program to evaluate abandoned USTs at the Birmingham AANG facility included identifying abandoned tank locations, sampling tank contents, preparing tank removal plans and specifications, removing tanks and contaminated soil, and evaluating investigation-derived wastes after the removal effort was complete.


During the Tank Survey Task to identify the location and sizes of the tank, magnetic devices and Ground Penetrating Radar (GPR) were used to identify tank boundaries and sizes. Two areas found during this task were believed to contain USTs. Hand augering to verify the tanks was not possible because of overlying concrete and asphalt.

Further review of aerial photography and base records revealed minimal information about the UST 211 site. UST 211 was included in the UST removal project.

Excavation for the tanks was performed in January 1991. The asphalt and concrete were removed and soil was excavated to a depth of 5.5 feet, to the top of the shallow rock formation. There was no indication of tanks. A 2" diameter line was found on the north side of the excavation and a 2½"diameter fill line was traced and found to extend under Building 211. Additional excavation was conducted on the north and west sides of Building 211 and no evidence of a UST was found. Because shallow rock formations are present in the area, it is expected that the tank was located aboveground.

Three soil samples were taken from the excavations at the UST 211 site. These soil samples did not indicate the presence of fuel component organic compounds. In addition, field screening tests (headspace readings) were conducted with a photoionization detector, manufactured by HNu systems, to screen the soils associated with the fuel systems. Soil samples were placed in glass jars and covered with foil to create a headspace in the top half of the jar. The HNu probe was inserted through the foil cover into the headspace, approximately 5 minutes after sampling, to indicate if any volatile organic compounds (VOCs) were present in the soil sample.





HNu HEADSPACE READING							
LOCATION	(ppm)						
211-N 211-E 211-W 211-SP W-1	5.0 1.2 2.0 170						

OLD PUMP ISLAND

LOCATIONS

FIGURE 3
UST 211 SITE MAP
Alabama Air National Guard, Birmingham, Alabama

3. CONTROL MEASURES

Because UST 211 was not found, control measures used to consider the adverse effects from potential contamination were not considered for screening, identification, and evaluation.

4. CONCLUSIONS

Past operations at the UST 211 site led to this investigation because of possible soil and water contamination. A field survey task used to identify the UST's location did not reveal the presence of a UST at this site. On the basis of information found during the UST removal project, it is believed that the UST was previously removed or that the UST exists under Building 211. Discussions with Alabama Department of Environmental Management (ADEM) field personnel indicated that no additional excavation would be required. ADEM documentation is included in the Appendix.

Because no UST was found and soil samples collected did not contain fuel contamination, it is recommended that this site be removed from further IRP activities and that no further action be required.

Signature:		Date:	
-	DAVID C. VAN GASBECK Chief, Environmental Division Air National Guard Readiness Center		
Signature:	Da	te:	
	Alahama Department of Environmental Manager	ment	

Appendix
ADEM Response to Closure Assessment Report

ADEM

ALABAMA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT



Guy Hunt Governor

Leigh Pegues, Director

May 8, 1991

1751 Cong. W. L. Dickinson Drive Montgomery, AL 36130 (205) 271-7700 FAX 271-7950 270-5612

35209 (205) 942-6168

FAX 941-1603

P.O. Box 953

Decatur, AL 35602

(205)353-1713

2204 Perimeter Road

FAX 340-9359

Mobile, AL

(205)479-2336

FAX 479-2593

36615

Colonel Jim Copeland Alabama Air National Guard East Lake Boulevard Birmingham, Alabama 35217-3595

Dear Colonel Copeland:

Field Offices:

RE: 117th Recon, East Lake Boulevard, Birmingham, Jefferson County, Alabama
Facility Not Registered
UST380, 211A and 211B

The Department has reviewed the underground storage tank closure assessment for the referenced site. As a result of this review it is determined that no further investigative or corrective actions will be required for this site at this time.

Please use a complete reference line in all future correspondence, including Facility Identification Number, name, address, and Incident Number (UST - -), where applicable. Sites that are not registered will not have an Identification Number and should be labeled (NOT REGISTERED). Because our filing system is dependent on the use of the Facility Identification Number, we may have to return correspondence and reports that do not provide this information.

If there are any questions, please contact me at 205/271-7835.

Sincerely

Thadous W. Pittman
Environmental Scientist
Groundwater Branch
Water Division

TWP/cmh